## KLIK STAIRWELL TOWER ERECTION INSTRUCTIONS MANUFACTURED TO A TUV CERTIFIED ISO 9001 QUALITY SYSTEM

## ENSURE ALL PARTS ARE PRESENT BEFORE ERECTION

- 6. Dismantling is the reverse of assembly.
- 5. Position the platform with the trapdoor to the front and Klik in four horizontal braces and fit Toeboards as shown using the 3T method creating the Guardrail.
- 4. Add ladder frame and engage interlock clips.
- 3. Klik in upper diagonal brace.
- Klik in horizontal brace above designated locating collar, level tower by using the adjustable legs.
   Klik in lower diagonal brace as shown.
- 1. Insert adjustable legs into frame



ALWAYS CLIMB ON THE INSIDE OF THE TOWER

MAX SAFE WORKING LOAD FOR PLATFORM/STRUCTURE 150 KG